

WHERE TO FIND REQUIRED CHANGES IN CWEP DRAFT PRETREATMENT ORDINANCE

PRETREATMENT STREAMLINING RULE CHANGES THAT ARE REQUIRED	SECTION OF CWEP DRAFT PRETREATMENT ORDINANCE
Updated Removal Credits Provisions for CSOs [SS403.7(h)]	NA
Slug Control Requirements Included in SIU Control Mechanisms [SS403.8 (f)(1)(iii)(B)(6)]	Section 4.9.A.6
Evaluate SIUs for Need For Plan or Other Action to Control Slug Discharges w/in Year of Rule [SS403.8(f)(2)(vi)]	NA
SIUs to Notify POTW Immediately of Facility Changes Affecting Potential for Slug Discharge [SS403.8(f)(2)(vi)]	Section 4.15.5.C
Expanded Definition of Significant Noncompliance [SS403.8(f)(2)(viii)(A-C)]	Section 4.23.A. - C.
SIU Reports Must Include BMP Compliance Information [SS403.12(b), (e), (h)]	Section 4.15.4.A
SIU Control Mechanisms Must Contain BMPs Req'd by Pretreatment Std, Local Limits, etc. [SS403.8(f)(1)(iii)(B)(3)]	Section 4.9.A.3
Documentation of Compliance w/BMP Reqmts to be Maintained as Part of SIU and POTW Record Keeping Reqmts [SS403.12(o)]	Section 4.15.8
Control Authorities Performing SIU Sampling Must Perform Req'd Repeat Sampling & Analysis w/in 30 Days [SS403.12(g)(12)]	Section 4.15.4.E
Sampling Reqmts for Periodic Compliance Reports, etc. [SS403.12(g)(3), (4), (6)]	Section 4.21.A., C.
Non-Categorical SIUs Req'd to Provide Representative Samples in Periodic Monitoring Reports [SS403.12(g)(3)]	Section 4.15.4.D
Require Notification of Changed Discharge to Control Authority & POTW, When POTW is not the Control Authority [SS403.12(j)]	NA
How, When POTW can Designate a "Duly Authorized Employee" to Sign POTW Reports [SS403.12(m)]	NA